



SIMCom Wireless Solutions Ltd.
A SIM Technology Bldg., 633 Jinzhong Road, Changning District, Shanghai PRC
Tel: 86 21 32523300 Fax 86 21 32523020 Zip: 200335

To whom it may concern,

Dear sir/madam,

SIMCom Wireless Solutions Ltd decides to stop the production of SIM800 M64 (S2-105MC series), due to chipset shortage from supplier side. We suggest to use the following products as the replacement of SIM800 M64: SIM800 M32 (S2-105MB series), SIM800F, SIM800C.

Best Regards,

Name: Yongsheng Li



Title: Vice General Manager

Shanghai SIMCom Wireless Solutions Ltd